

# Volkswagen Cabriolet

## DIY Guide: Fuel Gauge Sender Float

### Symptoms:

- Fuel gauge reading low despite a full tank
- Fuel gauge stuck on empty

### Cause:

- If the gauge and sender test good, the float may be compromised and has filled with fuel



### Remedy:

- Replace float (seen below)
  - [Omix-ADA part #17729.01](#) (alternate part numbers: RR1238862, 5357373-F)
    - This is a Jeep component, but works in a Cabriolet!
- Repairing float is possible, but may not last long

